

Amendment 02/29/16 - Items 12 and 15: NO AWARD



Town Hall · 100 Main Street
Huntington, NY 11743-6991

Phone: (631) 351-3177
Fax: (631) 351-2833
<http://HuntingtonNY.gov>

Lori E. Finger, CPPB
Director of Purchasing

For additional informtion contact
purchasing@huntingtonny.gov

Denise Gallo
Purchasing Agent

**AWARD: REPLACEMENT AND OR REPAIRS OF VARIOUS WASTEWATER TREATMENT PLANT
EQUIPMENT PARTS
BID NO. TOH 15-09R-044
BID OPENED: 09/10/15
CONTRACT PERIOD: 10/29/15 TO AND INCLUDING 09/30/16
CONTRACT EXTENSION PERIOD: 10/01/16 TO AND INCLUDING 09/30/17
CATEGORY #9: ENVIRONMENTAL SERVICES, RECYCLING AND REFUSE SERVICES
ALL PRICES ARE FOB TOWN OF HUNTINGTON**

AWARDEES:

- #9797/3 GP Jager Inc. Tel: 973-750-1180
 PO Box 417 Fax: 973-750-1181
 Butler, NJ 07405 zstolc@jagerinc.com
 Attn: Zuzanna Stolc, Office Manager
- #476 Jack Doheny Companies, Inc. Tel: 248-349-0904
 777 Doheny Drive, P.O. Box 609 Fax: 248-349-2774
 Northville, MI 48167 richardhughes@dohenycompanies.com
 Attn: Richard Hughes, VP Municipal Sales
- #16249 Koester Associates, Inc. Tel: 315-697-3800
 3101 Seneca Turnpike Fax: 315-697-3888
 Canastota, NY 13031 rich@koesterassociates.com
 Attn: Mark Koester, President
- #15972 Rapid Pump & Meter Service Co. Inc. Tel: 973-345-5600
 P.O.Box AY Fax: 973-345-0301
 Paterson, NJ 07509 richtaylor@servicer.com
 Attn: Rich Taylor, President

Pursuant to New York General Municipal Law §103(16), the contract awarded hereby shall be made available to other New York State governmental entities and, therefore, any New York State officer, board or agency of a political subdivision or of any district therein authorized to make purchases of apparatus, materials, equipment or supplies, or to contract for services related to the installation, maintenance, or repair of apparatus, materials, equipment or supplies, may make such purchases, or may contract for such services through the use of this contract. Said entities using this contract shall be wholly responsible for the determination that the contract meets their requirements and for the issuance of said contract and shall be solely responsible for the payment of any and all debts and claims that arise thereunder.



| | | | | | Vendor | Price/Percentage |
|---|----------------|--|------------------|-----------------------------------|---------------------------------|------------------|
| Section #1: Supply replacement parts for BDP belt press parts 1.5m BDP (Job # 760) belt filter price (1987) Price per Unit | | | | | | |
| Parts: | | | | | | |
| BDP MANUFACTURED WEAR ITEMS | REQD PER PRESS | MANUFACTURER | PART NUMBER | DESCRIPTION | | |
| 1-1 | 1 | BDP | 3-610-524 (P2) | SET OF (2) DOCTOR BLADES | NO EXTENSION BEING READVERTISED | |
| 1-2 | 1 | BDP | 1-BDP-0025 | FEEDBOX SEAL | NO EXTENSION BEING READVERTISED | |
| 1-3 | 1 | BDP | 3-610-1120 | SET OF (2) GUIDE RAIL SEALS | NO EXTENSION BEING READVERTISED | |
| 1-4 | 1 | BDP | 1-BDP-0032 (60") | SET OF (2) TOP SHOWER SEALS | NO EXTENSION BEING READVERTISED | |
| 1-5 | 1 | BDP | 1-BDP-0033 (60") | SET OF (4) BOTTOM SHOWER SEALS | NO EXTENSION BEING READVERTISED | |
| 1-6 | 2 | BDP | 3-310-89 | TRACKING SLIDE PLATES | NO EXTENSION BEING READVERTISED | |
| 1-7 | 4 | BDP | 3-610-842 (P1) | TRACKING PADDLE | NO EXTENSION BEING READVERTISED | |
| 1-8 | 5 | BDP | 3-650-74 | 3" NYLON TABLE ROLL | NO EXTENSION BEING READVERTISED | |
| 1-9 | 12 | BDP | 3-610-871 | 6" NYLON COMPRESSION /IDLER ROLL | NO EXTENSION BEING READVERTISED | |
| 1-10 | 2 | BDP | 3-610-1238 | 6" NITRILE TRACKING ROLL | NO EXTENSION BEING READVERTISED | |
| 1-11 | 6 | BDP | 3-610-1049 | 8" NYLON COMPRESSION /IDLER ROLL | NO EXTENSION BEING READVERTISED | |
| 1-12 | 3 | BDP | 3-610-963 | 10" NYLON COMPRESSION /IDLER ROLL | NO EXTENSION BEING READVERTISED | |
| 1-13 | 1 | BDP | 3-610-1615 | 20" NITRILE DRIVE ROLL | NO EXTENSION BEING READVERTISED | |
| 1-14 | 1 | BDP | 2-610-165 | 24" PERFORATED ROLL | NO EXTENSION BEING READVERTISED | |
| 1-15 | N/A | Any part not listed for BDP belt press - % Above Manufacturers List Cost | | | NO EXTENSION BEING READVERTISED | |

| | | | Vendor | Price/Percentage |
|---|---|---------------------|----------|------------------|
| Section #2: Flowserve Actuator Limitorque Accutronix | | | | |
| Parts and Labor: | | | | |
| 2-1 | Percentage off Manufacturers List Price for materials | | NO AWARD | |
| 2-2 | Labor Cost to Repair Listed Equipment | | | |
| 2-2a | Mechanic: /HR | | NO AWARD | |
| | Helper: /HR | | NO AWARD | |
| 2-2b | Labor Rates (Weekends and Holidays) | | | |
| | Mechanic: /HR | | NO AWARD | |
| | Helper: /HR | | NO AWARD | |
| Section #3: Envirosight Rover 5.0 Motorized Robotic Color Camera. Rover 600 and TR 150 | | | | |
| Parts and Labor: | | | | |
| 3-1 | Percentage off Manufacturers List Price for materials | | NO AWARD | |
| | Labor Cost to Repair Listed Equipment | | | |
| 3-2 | Bench Charge: /HR | | NO AWARD | |
| Section #4: Penn Valley Model 4" Double Disc Pump - Price Per | | | | |
| Item # | Description | Part# | | |
| 9-1 | Suction Housing | PVC101 | NO AWARD | |
| 9-2 | Intermediate Housing | PVC102 | NO AWARD | |
| 9-3 | Discharge Housing | PVC103 | NO AWARD | |
| 9-4 | Swan Neck , Cast Iron | PVC104 | NO AWARD | |
| 9-5 | Pedestal | PVB106 | NO AWARD | |
| 9-6 | Center Support | PVB107 | NO AWARD | |
| 9-7 | Drive Shaft | PVB108 | NO AWARD | |
| 9-8 | Cam Lobe | PVA109 | NO AWARD | |
| 9-9 | Con Rod Suction | PVC110A | NO AWARD | |
| 9-10 | Con Rod , Discharge | PVC110B | NO AWARD | |
| 9-11 | Drive Rod , Suction | PVA111 | NO AWARD | |
| 9-12 | Drive Rod , Discharge | PVA112 | NO AWARD | |
| 9-13 | Trunnion | PVB113 | NO AWARD | |
| 9-14 | Trunnion Clamp Ring , Suction | PVB114A | NO AWARD | |
| 9-15 | Trunnion Clamp Ring , Discharge | PVB114B | NO AWARD | |
| 9-16 | Integral Disc, Suction | PVC188 or PVD632 | NO AWARD | |
| 9-17 | Integral disc, Discharge | PVC160 or PVD633 | NO AWARD | |
| 9-18 | Gasket , Suction | PVB119 | NO AWARD | |
| 9-19 | Gasket , Discharge | PVB120 | NO AWARD | |
| 9-20 | Clack Valve | PVB121 | NO AWARD | |
| 9-21 | Clack Valve Spacer | PVA122 | NO AWARD | |
| 9-22 | Special Washer | PVA138 | NO AWARD | |
| 9-23 | Drive Pin | PVA182 | NO AWARD | |
| 9-24 | Bearing Con Rod | PVA242 | NO AWARD | |
| 9-25 | Bearing Pedestal | PVA245 | NO AWARD | |
| 9-26 | Drive Cover | PVB123 | NO AWARD | |
| 9-27 | Priming/Drain Plug | PVA180 | NO AWARD | |
| 9-28 | 1/2"-13 UNCx5" Bolt | PVA390 | NO AWARD | |
| 9-29 | 1/2"-13 UNCx3-1/4" Bolt | PVA389 | NO AWARD | |
| 9-30 | 1/2"-13 UNCx2-1/4" Bolt | PVA388 | NO AWARD | |
| 9-31 | 1/2"-13 UNC Nut | PVA386 | NO AWARD | |
| 9-32 | 1/2" Flat Washer | PVA385 | NO AWARD | |
| 9-33 | 1/2" Lock Washer | PVA384 | NO AWARD | |
| 9-34 | 1/2"-13 UNC x 2" Bolt | PVA387 | NO AWARD | |
| 9-35 | 5/16"-18x3/4" Bolt | PVA383 | NO AWARD | |
| 9-36 | 5/16" Flat Washer | PVA382 | NO AWARD | |
| 9-37 | 5/16" Lock Washer | PVA381 | NO AWARD | |

| | | | Vendor | Price/Percentage |
|---|---|--------------|------------------------------------|------------------|
| Section #5: Essco Pump Model # 4 x 12 - hdpc horizontal dry pit (Serial #6128) | | | | |
| Parts: | | | | |
| 5-1 | Percentage off Manufacturers List Price for materials | | Koester Associates, Inc. | 25% |
| Section #6: Repairs and parts Vactor, Jet Rodder, Guzzler Combo unit, and Godwin 6 inch Diesel pump . This section of the bid is for mechanical repairs for WWTP road and pumping equipment. | | | | |
| Additional specifications for this section: | | | | |
| Labor: Labor to diagnose, mechanical repairs, replace, rebuild, refurbish, weld, fabricate, wwtp road service equipment, and pumping equipment listed above. A 1 (one) year or 12,000 mile warranty on labor from any defection work, labor doesn't cover defective or abused or worn parts. | | | | |
| Parts: If mechanical parts are needed, for Town of Huntington WWTP equipment, a decision to supply or have fendor supply parts. No used parts will be excepted only new or remanufactured parts will be accepted. | | | | |
| 6-1 | Percentage off Manufacturers List Price for materials | | Jack Doheny Companies, Inc. | 10% |
| 6-2 | Labor Cost to Repair Listed Equipment /Per Hour | | Jack Doheny Companies, Inc. | \$120.00 |
| 6-3 | Emergency Road Service Repairs /Per Hour | | Jack Doheny Companies, Inc. | \$120.00 |
| Section #7: Supply replacement for Trogan UV3000 Plus unit | | | | |
| Price Per Unit | | | | |
| Item # | Decription | Part # | | |
| 7-1 | Lamp holder, Amalgam 4 wire 60" | 316135-060 | NO AWARD | |
| 7-2 | Lamp holder, Amalgam 4 wire 78" | 316135-078 | NO AWARD | |
| 7-3 | Lamp holder, Amalgam 4 wire 96" | 316135-096 | NO AWARD | |
| 7-4 | Lamp holder, Angular Amalgam 4 wire 60" | 316473-060 | NO EXTENSION BEING READVERTISED | |
| 7-5 | Lamp holder, Angular Amalgam 4 wire 78" | 316473-078 | NO EXTENSION BEING READVERTISED | |
| 7-6 | Lamp holder, Angular Amalgam 4 wire 96" | 316473-096 | NO EXTENSION BEING READVERTISED | |
| 7-7 | Lamp, Hareus Amalgam (salmon colored base) (4 recommended, 24 supplied with system) | 794447 | NO EXTENSION BEING READVERTISED | |
| 7-8 | Sleeve, Quartz, 28mmx25mmx1850mm domed, | 316136 | NO EXTENSION BEING READVERTISED | |
| 7-9 | Plug, UV3 + PDC Module 6' | 914374-006 | NO EXTENSION BEING READVERTISED | |
| 7-10 | Spring, SS Compression | 901376 | NO EXTENSION BEING READVERTISED | |
| 7-11 | Sleeve cup nut | 316148 | NO EXTENSION BEING READVERTISED | |
| 7-12 | O-Ring Seal | 316168 | NO EXTENSION BEING READVERTISED | |
| 7-13 | O-Ring, Sleeve Support (4 Recommended) | 316144 | NO EXTENSION BEING READVERTISED | |
| 7-14 | O-Ring, Sleeve Support | 316145 | NO EXTENSION BEING READVERTISED | |
| 7-15 | Coupling, Female | 013168-04FST | NO AWARD | |
| 7-16 | Coupling, Male | 013169-04MST | NO AWARD | |
| 7-17 | Rubber Dust Collector, Female | 013199-04F | NO AWARD | |
| 7-18 | Rubber Dust Collector, Male | 013200-04M | NO AWARD | |

| | | | Vendor | Price/Percentage |
|------|---|--------------------|------------------------------------|-------------------------|
| 7-19 | Hydraulic Hose ASY, Retract, LS (Black) | 907424-04F071BK | NO AWARD | |
| 7-20 | Hydraulic Hose ASY, Extend, LS (Black) | 907424-04M150BK | NO AWARD | |
| 7-21 | Hydraulic Hose ASSY, Retract, RS (Blue) | 907424-04F145BL | NO AWARD | |
| 7-22 | Hydraulic Hose ASSY, Extend, RS (Blue) | 907424-04M066BL | NO AWARD | |
| 7-23 | Hydraulic Tube Extend, SS, 4 Lamp Modules | 326417-430-435-440 | NO EXTENSION BEING READVERTISED | |
| 7-24 | Hydraulic Tube Retract, SS, 4 Lamp Modules | 326418-430-435-440 | NO EXTENSION BEING READVERTISED | |
| 7-25 | Nut, Locking Bar Lock Brackets | O11047 | NO EXTENSION BEING READVERTISED | |
| 7-26 | Screw, Lock Brackets and Drive Bar Mount | O10314-AAf083160 | NO EXTENSION BEING READVERTISED | |
| 7-27 | Lock Washer, Sensor Drive Bar Brackets | O12014 | NO EXTENSION BEING READVERTISED | |
| 7-28 | Wiper Bracket, Upper | 327766-UPR | NO EXTENSION BEING READVERTISED | |
| 7-29 | Wiper Bracket, Lower | 327766-LWR | NO EXTENSION BEING READVERTISED | |
| 7-30 | Bracket, Sensor Lock | 327132 | NO EXTENSION BEING READVERTISED | |
| 7-31 | Lock Plate, Drive Bar | 327130 | NO EXTENSION BEING READVERTISED | |
| 7-32 | Cylinder, Wiper | 326411 | NO EXTENSION BEING READVERTISED | |
| 7-33 | Grease, Food Grade (1 Recommended, 1 Supplied with System) | OO5066 | NO EXTENSION BEING READVERTISED | |
| 7-34 | Grease, Nipple | 326399 | NO EXTENSION BEING READVERTISED | |
| 7-35 | Grease Gun | 5067 | NO AWARD NO EXTENSION | |
| 7-36 | Fitting, Plastic (2 Per Canister) | 327027 | NO EXTENSION BEING READVERTISED | |
| 7-37 | Fitting, Plastic 90 degree elbow | 327066 | NO EXTENSION BEING READVERTISED | |
| 7-38 | Seal Kit UV3000Plus - Plastic Canister (1 Recommended) | 327122 | NO EXTENSION BEING READVERTISED | |
| 7-39 | Tube, 1/4 diameter Viton | 327030 | NO EXTENSION BEING READVERTISED | |
| 7-40 | Cap Removal Tool (UV3 + Wiper End Cap Tool) | 327126 | NO EXTENSION BEING READVERTISED | |
| 7-41 | Plug, Rubber Wiper Filler (Top vent and bottom filler) (Qty 2 per module) | 327095 | NO EXTENSION BEING READVERTISED | |
| 7-42 | Screw, Top Vent (Sensor Only) | O10313-AAFO63160 | NO EXTENSION BEING READVERTISED | |
| 7-43 | Washer, Upper and Lower brackets | O10116 | NO EXTENSION BEING READVERTISED | |
| 7-44 | Lock Washer, Drive Bar Mount, 1/4" | O10035 | NO EXTENSION BEING READVERTISED | |
| 7-45 | Screw, Drive Bar Mount | O10362 | NO EXTENSION BEING READVERTISED | |

| | | | Vendor | Price/Percentage |
|------|--|--------------|------------------------------------|-------------------------|
| 7-46 | Valve, Rubber Wiper relief, 4-7 PSI | 445044 | NO EXTENSION BEING READVERTISED | |
| 7-47 | Adaptor, Pressure Relief | 327765 | NO EXTENSION BEING READVERTISED | |
| 7-48 | Washer, Flat | O12071 | NO AWARD | |
| 7-49 | Module Board Kit | 914385 | NO EXTENSION BEING READVERTISED | |
| 7-50 | Board, UV3 + MCB 220-227V | 912356-001 | NO AWARD | |
| 7-51 | Desiccant, DESI PAK 1/6 Unit | 302366 | NO AWARD | |
| 7-52 | Lubricant, Dow 111 5 g Pak | OO3084 | NO AWARD | |
| 7-53 | Seal, End Cap Ballast Enclosure UV3+ (1 recommended) | 316479 | NO AWARD | |
| 7-54 | INSTN, Module Board Replacement | 914383 | NO AWARD | |
| 7-55 | Ballast Kit (1 Recommended, 4 ballast supplied with system) | 914384 | NO AWARD | |
| 7-56 | Ballast, UV3+ Standard | 903988-001 | NO AWARD | |
| 7-57 | Desiccant, DESI PAK 1/6 UNIT | 302366 | NO AWARD | |
| 7-58 | Lubricant, Dow 111 5 g Pack | OO3084 | NO AWARD | |
| 7-59 | Strain Relief, 1/2" C/W O-ring | 302456 | NO EXTENSION BEING READVERTISED | |
| 7-60 | Screw, 5/16-18x1/2" Allen Head | 303314 | NO EXTENSION BEING READVERTISED | |
| 7-61 | O-Ring 1/4 x 3/32 Nitrile UL | 002226-108UL | NO EXTENSION BEING READVERTISED | |
| 7-62 | Desiccant, DESI PAK 1/6 UNIT | 302366 | NO AWARD | |
| 7-63 | Instruction, UV3 + End cap replacement | 316492 | NO AWARD | |
| 7-64 | Spacer Clips | 329226 | NO EXTENSION BEING READVERTISED | |
| 7-65 | Screw (Spacer Clip) 6-32x3/5 S- Tap Phillips | O10011 | NO EXTENSION BEING READVERTISED | |
| 7-66 | Hydraulic Filter (1 Recommended) | 907384 | NO EXTENSION BEING READVERTISED | |
| 7-67 | Contactora, 12A Schneider Mini | 914287 | NO EXTENSION BEING READVERTISED | |
| 7-68 | Contactora, O/L 380-480V | 914289-003 | NO EXTENSION BEING READVERTISED | |
| 7-69 | Contactora, O/L 208V | 914289-005 | NO EXTENSION BEING READVERTISED | |
| 7-70 | PLC, TWIDO, compact 2410 | 913292-110 | NO EXTENSION BEING READVERTISED | |
| 7-71 | Fuse Block, 1P | 912579 | NO EXTENSION BEING READVERTISED | |
| 7-72 | Fuse Block, 3P | 912789 | NO EXTENSION BEING READVERTISED | |
| 7-73 | Fuse, 6A Class CC (1 Recommended, 24 supplied with system) | 913838 | NO EXTENSION BEING READVERTISED | |

| | | | Vendor | Price/Percentage |
|------|--|----------------|------------------------------------|-------------------------|
| 7-74 | Fuse, 4A Class CC (1 Recommended, 24 supplied with system) | 912932 | NO EXTENSION BEING READVERTISED | |
| 7-75 | Hydraulic fluid, Tellus, 20L (1 Recommended, 1 Supplied with system for commissioning) | 444295 | NO EXTENSION BEING READVERTISED | |
| 7-76 | Gas Door Struts - 30 lb | 901711-30 | NO EXTENSION BEING READVERTISED | |
| 7-77 | Gas Door Struts - 40 lb | 901711-40 | NO AWARD | |
| 7-78 | Gas Door Struts - 50 lb | 901711-50 | NO AWARD | |
| 7-79 | Gas Door Struts - 60 lb | 901711-60 | NO AWARD | |
| 7-80 | Low Level Sensor Module 24 VDC | 914345-001 | NO EXTENSION BEING READVERTISED | |
| 7-81 | Power Supply, 10A 24 VDC | 914277 | NO EXTENSION BEING READVERTISED | |
| 7-82 | Relay 16A 3P Touch Safe (1 recommended, 24 supplied with system) | 914341 | NO EXTENSION BEING READVERTISED | |
| 7-83 | Relay, 15A Base | 912806 | NO EXTENSION BEING READVERTISED | |
| 7-84 | Receptavle, UV3 + 2007 | 914343 | NO EXTENSION BEING READVERTISED | |
| 7-85 | Receptavle, UV3 + PDC cap | 914368 | NO EXTENSION BEING READVERTISED | |
| 7-86 | Fuse Block, 1 P | 912579 | NO AWARD | |
| 7-87 | Fuse Block, 3P | 912789 | NO AWARD | |
| 7-88 | Fuse, 15A class CC (1 recommended, 24 supplied with system) | 913420 | NO EXTENSION BEING READVERTISED | |
| 7-89 | Fuse, 6A Class CC (1 Recommended, 24 supplied with system) | 912333 | NO EXTENSION BEING READVERTISED | |
| 7-90 | Board ASY, UV3+CCB (kit) | 931092 | NO EXTENSION BEING READVERTISED | |
| 7-91 | Board, UV3+CCB (See 7-90) | 931086 | NO AWARD | |
| 7-92 | ActicleanGel (1 Recommended, 1 Supplied with system) | 901507 | NO EXTENSION BEING READVERTISED | |
| 7-93 | Pressure Injector, Gel UV3 + PLG | 327096 | NO EXTENSION BEING READVERTISED | |
| 7-94 | Injector Tip Fitting, 90 degree Elbow (See 7-37) | 327066 | NO AWARD | |
| 7-95 | Safeguard M-1, Rust inhibitor (kit) (1 Recommended 1 supplied with system) | 331004 | NO AWARD | |
| 7-96 | Safeguard M-1, Rust inhibitor, 0.95L | 331003 | NO AWARD | |
| 7-97 | Bottle Spray, Polyethylene | 110156 | NO AWARD | |
| 7-98 | Sensor ASSY, UV3 + NIST9c/w box | 015393-S-158NB | NO EXTENSION BEING READVERTISED | |

| | | | Vendor | Price/Percentage |
|-------|---|------------------|------------------------------------|-------------------------|
| 7-99 | Sensor Shipping Box | O15378 | NO AWARD | |
| 7-100 | Sensor Rear Mount Kit (Complete with Cable ASSY) (See 7-98) | O15393-S-158NB | NO AWARD | |
| 7-101 | Sensor Rear Mount Kit (No Cable ASSY) | O15403-002 | NO EXTENSION BEING READVERTISED | |
| 7-102 | Sensor Cable Kit, UV3 + NIST (c/w cable and grommet) | O15406 | NO EXTENSION BEING READVERTISED | |
| 7-103 | Sensor Mount screw, #8-32x1/2" | O10330-83A8C1088 | NO EXTENSION BEING READVERTISED | |
| 7-104 | Lock washer, #8 (for retaining screw) | 700126 | NO EXTENSION BEING READVERTISED | |
| 7-105 | Sensor Sleeve | O15239 | NO EXTENSION BEING READVERTISED | |
| 7-106 | Washer, Sensor Sleeve | O15244 | NO EXTENSION BEING READVERTISED | |
| 7-107 | O-Ring, Sleeve Seal (1 recommended) (See 7-13) | 316144 | NO AWARD | |
| 7-108 | Sleeve Cup Nut (See 7-11) | 316148 | NO AWARD | |

| | | | Vendor | Price/Percentage |
|--|---|-------------|------------------------------------|-------------------------|
| 7-109 | Bracket ASSY, 4.0" Spacing | O15237-400 | NO EXTENSION BEING READVERTISED | |
| 7-110 | Sensor Cable Kit Trojan (See-102) | 15406 | NO AWARD | |
| 7-111 | Uv3+ccb processor board Trojan (See 7-90) | 931087 | NO AWARD | |
| 7-112 | Any part not listed for the Trojan 3000 plus UV | N/A | NO AWARD | |
| Section #8: Aqua-Aerobic System (AquaSBR) Sequencing Batch Reactor Price per Unit | | | | |
| Item # | Description | Part # | | |
| 8-1 | Actuator, Limitorque Accutronix, Model LY 2001 (115 VAC) | 91070453047 | GP Jager Inc. | \$13,271.93 |
| 8-2 | Actuator, Limitorque Accutronix, Model LY-3001 (115 VAC) | 91070453048 | GP Jager Inc. | \$13,794.03 |
| 8-3 | Actuator, Limitorque Accutronix, Model MX (460 VAC) | 91070453049 | GP Jager Inc. | \$21,609.25 |
| 8-4 | Level Transducer, Keller Model 700 | 2610523 | GP Jager Inc. | \$828.70 |
| 8-5 | Linear Actuator, 1500# | 2603972 | GP Jager Inc. | \$1,199.49 |
| 8-6 | Capacitor, 35 MFU | 2605100 | GP Jager Inc. | \$105.06 |
| 8-7 | Limit Switch (Micro Switch) | 26007598 | GP Jager Inc. | \$615.08 |
| 8-8 | Limit Switch Level Arm | 2600926 | GP Jager Inc. | \$43.32 |
| 8-9 | Membrane Kit (Gummi-Jager) | 2962546 | GP Jager Inc. | \$36.74 |
| 8-10 | Seal Grommet, #S-114 | 2609887 | GP Jager Inc. | \$4.52 |
| 8-11 | Upper Wedge Cap, #W-114 | 2609885 | GP Jager Inc. | \$11.26 |
| 8-12 | Pincer, Straight Jaw (Oetiker) | 2608035 | GP Jager Inc. | \$38.32 |
| 8-14 | Touch Up Kit - Tenemec 46H-413 | 91070453055 | GP Jager Inc. | \$201.92 |
| 8-15 | In Put Card, 16 Point Relay | 2607722 | GP Jager Inc. | \$339.58 |
| 8-16 | Analog Input Card, 8 Point | 2750148 | GP Jager Inc. | \$1,055.02 |
| 8-17 | Power Supply, IO Rach | 2608994 | GP Jager Inc. | \$747.92 |
| 8-18 | Panelview 1000 Display | 2701264 | GP Jager Inc. | \$9,295.71 |
| 8-19 | Control Relay, SPDT | 2700940 | GP Jager Inc. | \$19.42 |
| 8-20 | EEPROM | 2750267 | GP Jager Inc. | \$595.94 |
| 8-21 | SLC 5/04 Programmable Controller | 2700703 | GP Jager Inc. | \$2,676.20 |
| 8-22 | Any part not listed for the Aqua- Aerobic system (AquaSBR) Sequencing Batch Reactor) - % Above Manufacturers List Cost Letterhead Quote | N/A | GP Jager Inc. | 0% |

| | | | Vendor | Price/Percentage |
|---|--|--|-------------------------------------|------------------|
| Section #9: Xylem brand Flygt pumps | | | | |
| Parts and Labor: | | | | |
| 9-1 | Percentage off Manufacturers List Price for materials | | NO EXTENSION BEING READVERTISED | |
| 9-2 | Labor Cost to Repair Listed | | | |
| 9-2a | Mechanic - /HR | | NO EXTENSION BEING READVERTISED | |
| | Helper - /HR | | NO EXTENSION BEING READVERTISED | |
| 9-2b | Labor Rates (Weekends and Holidays) | | NO EXTENSION BEING READVERTISED | |
| | Mechanic - /HR | | NO EXTENSION BEING READVERTISED | |
| | Helper - /HR | | NO EXTENSION BEING READVERTISED | |
| Section 10: Aerzen USA Corporation Blower Model # GM 25S - 00 DN-125 Pressure | | | | |
| 10-1 | Percentage off Manufacturers List Price for materials Letterhead Quote | | Rapid Pump & Meter Service Co. Inc. | 25% |
| Section 11: Supply parts for Atlas Copco Stationary compressors ZS 75+ VSD APF176732 | | | | |
| 11-1 | Percentage off Manufacturers List Price for materials | | NO AWARD | |
| Section 12: Komline-Sanderson Gravabelt GSC-2 Series #3 S-3935 Belt Filter Press | | | | |
| 12-1 | Percentage off Manufacturers List Price for materials Letterhead Quote | | NO AWARD | |
| Section #13: Supply parts for Duperon Corporation FlexRake FPFS Mechanically Cleaned Bar Screens S/N 914-1310-w2607-1, and 2 | | | | |
| 13-1 | Percentage off Manufacturers List Price for materials Letterhead Quote | | Koester Associates, Inc. | 0% |
| Section #14: Supply parts for Aurora pump Model # 612a 8x8x15a, and Models 341A, 342A, and 344A | | | | |
| 14-1 | Percentage off Manufacturers List Price for materials Letterhead Quote | | Rapid Pump & Meter Service Co. Inc. | 25.0% |
| Section #15: Supply parts for Komline-Sanderson K-S Plunger Pump Model # KSK-9-1 S/N 9KSK-43, and 9KSK-44 | | | | |
| 15-1 | Percentage off Manufacturers List Price for materials Letterhead Quote | | NO AWARD | |
| Section #16: Supply parts for Fairfield Cantenary Bar Screen (CHCFF) MN 80-31338 dated 12/12/14 | | | | |

| | | | Vendor | Price/Percentage |
|---|--|--|--------------------------|-------------------------|
| 16-1 | Percentage off Manufacturers List Price for materials Letterhead Quote | | GP Jager Inc. | 0% |
| Section #17: Supply parts for Duperon Corporation Washer Compactor SN: 202-1408-w2805-1 | | | | |
| 17-1 | Percentage off Manufacturers List Price for materials Letterhead Quote | | Koester Associates, Inc. | 0% |
| Section #18: Supply parts for Schloss Enginered Equipment Inc. Grit Chamber Dewatering Screw Project No. 1780-14 | | | | |
| 18-1 | Percentage off Manufacturers List Price for materials Letterhead Quote | | Koester Associates, Inc. | 0% |