

Amendment 02/29/16 - Items 12 and 15: NO AWARD



Town Hall · 100 Main Street
Huntington, NY 11743-6991

Phone: (631) 351-3177
Fax: (631) 351-2833
<http://HuntingtonNY.gov>

Lori E. Finger, CPPB
Director of Purchasing

For additional informtion contact
purchasing@huntingtonny.gov

Denise Gallo
Purchasing Agent

**AWARD: REPLACEMENT AND OR REPAIRS OF VARIOUS WASTEWATER TREATMENT PLANT
EQUIPMENT PARTS
BID NO. TOH 15-09R-044
BID OPENED: 09/10/15
CONTRACT PERIOD: 10/29/15 TO AND INCLUDING 09/30/16
CATEGORY #9: ENVIRONMENTAL SERVICES, RECYCLING AND REFUSE SERVICES
ALL PRICES ARE FOB TOWN OF HUNTINGTON**

AWARDEES:

- #1015 **Fleet Pump & Service Group, Inc.**
455 Knollwood Road
White Plains, NY 10603
Attn: Mark Cavanagh
Tel: 914-835-3801
Fax: 914-835-2946
mcavanagh@fleetpump.com

- #9797/3 **GP Jager Inc.**
PO Box 417
Butler, NJ 07405
Attn: Zuzanna Stolc, Office Manager
Tel: 973-750-1180
Fax: 973-750-1181
zstolc@jagerinc.com

- #476 **Jack Doheny Companies, Inc.**
777 Doheny Drive, P.O. Box 609
Northville, MI 48167
Attn: Richard Hughes, VP Municipal Sales
Tel: 248-349-0904
Fax: 248-349-2774
richardhughes@dohenycompanies.com

- #16249 **Koester Associates, Inc.**
3101 Seneca Turnpike
Canastota, NY 13031
Attn: Mark Koester, President
Tel: 315-697-3800
Fax: 315-697-3888
rich@koesterassociates.com

- #15972 **Rapid Pump & Meter Service Co. Inc.**
P.O.Box AY
Paterson, NJ 07509
Attn: Rich Taylor, President
Tel: 973-345-5600
Fax: 973-345-0301
richtaylor@servicer.com

Pursuant to New York General Municipal Law §103(16), the contract awarded hereby shall be made available to other New York State governmental entities and, therefore, any New York State officer, board or agency of a political subdivision or of any district therein authorized to make purchases of apparatus, materials, equipment or supplies, or to contract for services related to the installation, maintenance, or repair of apparatus, materials, equipment or supplies, may make such purchases, or may contract for such services through the use of this contract. Said entities using this contract shall be wholly responsible for the determination that the contract meets their requirements and for the issuance of said contract and shall be solely responsible for the payment of any and all debts and claims that arise thereunder.



					Vendor	Price/Percentage
Section #1: Supply replacement parts for BDP belt press parts 1.5m BDP (Job # 760) belt filter price (1987) Price per Unit Parts:						
BDP MANUFACTURED WEAR ITEMS	REQD PER PRESS	MANUFACTURER	PART NUMBER	DESCRIPTION		
1-1	1	BDP	3-610-524 (P2)	SET OF (2) DOCTOR BLADES	Fleet Pump & Service Group, Inc.	\$106.00
1-2	1	BDP	1-BDP-0025	FEEDBOX SEAL	Fleet Pump & Service Group, Inc.	\$84.00
1-3	1	BDP	3-610-1120	SET OF (2) GUIDE RAIL SEALS	Fleet Pump & Service Group, Inc.	\$90.00
1-4	1	BDP	1-BDP-0032 (60")	SET OF (2) TOP SHOWER SEALS	Fleet Pump & Service Group, Inc.	\$139.00
1-5	1	BDP	1-BDP-0033 (60")	SET OF (4) BOTTOM SHOWER SEALS	Fleet Pump & Service Group, Inc.	\$278.00
1-6	2	BDP	3-310-89	TRACKING SLIDE PLATES	Fleet Pump & Service Group, Inc.	\$56.00
1-7	4	BDP	3-610-842 (P1)	TRACKING PADDLE	Fleet Pump & Service Group, Inc.	\$50.00
1-8	5	BDP	3-650-74	3" NYLON TABLE ROLL	Fleet Pump & Service Group, Inc.	\$1,412.00
1-9	12	BDP	3-610-871	6" NYLON COMPRESSION /IDLER ROLL	Fleet Pump & Service Group, Inc.	\$2,389.00
1-10	2	BDP	3-610-1238	6" NITRILE TRACKING ROLL	Fleet Pump & Service Group, Inc.	\$2,556.00
1-11	6	BDP	3-610-1049	8" NYLON COMPRESSION /IDLER ROLL	Fleet Pump & Service Group, Inc.	\$2,889.00
1-12	3	BDP	3-610-963	10" NYLON COMPRESSION /IDLER ROLL	Fleet Pump & Service Group, Inc.	\$3,778.00
1-13	1	BDP	3-610-1615	20" NITRILE DRIVE ROLL	Fleet Pump & Service Group, Inc.	\$6,167.00
1-14	1	BDP	2-610-165	24" PERFORATED ROLL	Fleet Pump & Service Group, Inc.	\$11,667.00
1-15	N/A	Any part not listed for BDP belt press - % Above Manufacturers List Cost			Fleet Pump & Service Group, Inc.	0%

			Vendor	Price/Percentage
Section #2: Flowserve Actuator Limitorque Accutronix				
Parts and Labor:				
2-1	Percentage off Manufacturers List Price for materials		NO AWARD	
2-2	Labor Cost to Repair Listed Equipment			
2-2a	Mechanic: /HR		NO AWARD	
	Helper: /HR		NO AWARD	
2-2b	Labor Rates (Weekends and Holidays)			
	Mechanic: /HR		NO AWARD	
	Helper: /HR		NO AWARD	
Section #3: Envirosight Rover 5.0 Motorized Robotic Color Camera. Rover 600 and TR 150				
Parts and Labor:				
3-1	Percentage off Manufacturers List Price for materials		NO AWARD	
	Labor Cost to Repair Listed Equipment			
3-2	Bench Charge: /HR		NO AWARD	
Section #4: Penn Valley Model 4" Double Disc Pump - Price Per				
Item #	Description	Part#		
9-1	Suction Housing	PVC101	NO AWARD	
9-2	Intermediate Housing	PVC102	NO AWARD	
9-3	Discharge Housing	PVC103	NO AWARD	
9-4	Swan Neck , Cast Iron	PVC104	NO AWARD	
9-5	Pedestal	PVB106	NO AWARD	
9-6	Center Support	PVB107	NO AWARD	
9-7	Drive Shaft	PVB108	NO AWARD	
9-8	Cam Lobe	PVA109	NO AWARD	
9-9	Con Rod Suction	PVC110A	NO AWARD	
9-10	Con Rod , Discharge	PVC110B	NO AWARD	
9-11	Drive Rod , Suction	PVA111	NO AWARD	
9-12	Drive Rod , Discharge	PVA112	NO AWARD	
9-13	Trunnion	PVB113	NO AWARD	
9-14	Trunnion Clamp Ring , Suction	PVB114A	NO AWARD	
9-15	Trunnion Clamp Ring , Discharge	PVB114B	NO AWARD	
9-16	Integral Disc, Suction	PVC188 or PVD632	NO AWARD	
9-17	Integral disc, Discharge	PVC160 or PVD633	NO AWARD	
9-18	Gasket , Suction	PVB119	NO AWARD	
9-19	Gasket , Discharge	PVB120	NO AWARD	
9-20	Clack Valve	PVB121	NO AWARD	
9-21	Clack Valve Spacer	PVA122	NO AWARD	
9-22	Special Washer	PVA138	NO AWARD	
9-23	Drive Pin	PVA182	NO AWARD	
9-24	Bearing Con Rod	PVA242	NO AWARD	
9-25	Bearing Pedestal	PVA245	NO AWARD	
9-26	Drive Cover	PVB123	NO AWARD	
9-27	Priming/Drain Plug	PVA180	NO AWARD	
9-28	1/2"-13 UNCx5" Bolt	PVA390	NO AWARD	
9-29	1/2"-13 UNCx3-1/4" Bolt	PVA389	NO AWARD	
9-30	1/2"-13 UNCx2-1/4" Bolt	PVA388	NO AWARD	
9-31	1/2"-13 UNC Nut	PVA386	NO AWARD	
9-32	1/2" Flat Washer	PVA385	NO AWARD	
9-33	1/2" Lock Washer	PVA384	NO AWARD	
9-34	1/2"-13 UNC x 2" Bolt	PVA387	NO AWARD	
9-35	5/16"-18x3/4" Bolt	PVA383	NO AWARD	
9-36	5/16" Flat Washer	PVA382	NO AWARD	
9-37	5/16" Lock Washer	PVA381	NO AWARD	

			Vendor	Price/Percentage
Section #5: Essco Pump Model # 4 x 12 - hdpc horizontal dry pit (Serial #6128)				
Parts:				
5-1	Percentage off Manufacturers List Price for materials		Koester Associates, Inc.	25%
Section #6: Repairs and parts Vactor, Jet Rodder, Guzzler Combo unit, and Godwin 6 inch Diesel pump . This section of the bid is for mechanical repairs for WWTP road and pumping equipment.				
Additional specifications for this section:				
Labor: Labor to diagnose, mechanical repairs, replace, rebuild, refurbish, weld, fabricate, wwtp road service equipment, and pumping equipment listed above. A 1 (one) year or 12,000 mile warranty on labor from any defection work, labor doesn't cover defective or abused or worn parts.				
Parts: If mechanical parts are needed, for Town of Huntington WWTP equipment, a decision to supply or have fendor supply parts. No used parts will be excepted only new or remanufactured parts will be accepted.				
6-1	Percentage off Manufacturers List Price for materials		Jack Doheny Companies, Inc.	10%
6-2	Labor Cost to Repair Listed Equipment /Per Hour		Jack Doheny Companies, Inc.	\$120.00
6-3	Emergency Road Service Repairs /Per Hour		Jack Doheny Companies, Inc.	\$120.00
Section #7: Supply replacement for Trogan UV3000 Plus unit				
Price Per Unit				
Item #	Decription	Part #		
7-1	Lamp holder, Amalgam 4 wire 60"	316135-060	NO AWARD	
7-2	Lamp holder, Amalgam 4 wire 78"	316135-078	NO AWARD	
7-3	Lamp holder, Amalgam 4 wire 96"	316135-096	NO AWARD	
7-4	Lamp holder, Angular Amalgam 4 wire 60"	316473-060	Fleet Pump & Service Group, Inc.	\$47.00
7-5	Lamp holder, Angular Amalgam 4 wire 78"	316473-078	Fleet Pump & Service Group, Inc.	\$51.00
7-6	Lamp holder, Angular Amalgam 4 wire 96"	316473-096	Fleet Pump & Service Group, Inc.	\$67.00
7-7	Lamp, Hareus Amalgam (salmon colored base) (4 recommended, 24 supplied with system)	794447	Fleet Pump & Service Group, Inc.	\$325.00
7-8	Sleeve, Quartz, 28mmx25mmx1850mm domed,	316136	Fleet Pump & Service Group, Inc.	\$415.00
7-9	Plug, UV3 + PDC Module 6'	914374-006	Fleet Pump & Service Group, Inc.	\$97.00
7-10	Spring, SS Compression	901376	Fleet Pump & Service Group, Inc.	\$60.00
7-11	Sleeve cup nut	316148	Fleet Pump & Service Group, Inc.	\$30.00
7-12	O-Ring Seal	316168	Fleet Pump & Service Group, Inc.	\$45.00
7-13	O-Ring, Sleeve Support (4 Recommended)	316144	Fleet Pump & Service Group, Inc.	\$5.80
7-14	O-Ring, Sleeve Support	316145	Fleet Pump & Service Group, Inc.	\$0.51
7-15	Coupling, Female	013168-04FST	NO AWARD	
7-16	Coupling, Male	013169-04MST	NO AWARD	
7-17	Rubber Dust Collector, Female	013199-04F	NO AWARD	
7-18	Rubber Dust Collector, Male	013200-04M	NO AWARD	

			Vendor	Price/Percentage
7-19	Hydraulic Hose ASY, Retract, LS (Black)	907424-04F071BK	NO AWARD	
7-20	Hydraulic Hose ASY, Extend, LS (Black)	907424-04M150BK	NO AWARD	
7-21	Hydraulic Hose ASSY, Retract, RS (Blue)	907424-04F145BL	NO AWARD	
7-22	Hydraulic Hose ASSY, Extend, RS (Blue)	907424-04M066BL	NO AWARD	
7-23	Hydraulic Tube Extend, SS, 4 Lamp Modules	326417-430-435-440	Fleet Pump & Service Group, Inc.	\$29.00
7-24	Hydraulic Tube Retract, SS, 4 Lamp Modules	326418-430-435-440	Fleet Pump & Service Group, Inc.	\$29.00
7-25	Nut, Locking Bar Lock Brackets	O11047	Fleet Pump & Service Group, Inc.	\$2.00
7-26	Screw, Lock Brackets and Drive Bar Mount	010314-AAF083160	Fleet Pump & Service Group, Inc.	\$1.50
7-27	Lock Washer, Sensor Drive Bar Brackets	O12014	Fleet Pump & Service Group, Inc.	\$1.00
7-28	Wiper Bracket, Upper	327766-UPR	Fleet Pump & Service Group, Inc.	\$9.50
7-29	Wiper Bracket, Lower	327766-LWR	Fleet Pump & Service Group, Inc.	\$9.50
7-30	Bracket, Sensor Lock	327132	Fleet Pump & Service Group, Inc.	\$0.75
7-31	Lock Plate, Drive Bar	327130	Fleet Pump & Service Group, Inc.	\$1.75
7-32	Cylinder, Wiper	326411	Fleet Pump & Service Group, Inc.	\$1,334.00
7-33	Grease, Food Grade (1 Recommended, 1 Supplied with System)	OO5066	Fleet Pump & Service Group, Inc.	\$24.00
7-34	Grease, Nipple	326399	Fleet Pump & Service Group, Inc.	\$6.00
7-35	Grease Gun	5067	NO AWARD	
7-36	Fitting, Plastic (2 Per Canister)	327027	Fleet Pump & Service Group, Inc.	\$25.00
7-37	Fitting, Plastic 90 degree elbow	327066	Fleet Pump & Service Group, Inc.	\$41.00
7-38	Seal Kit UV3000Plus - Plastic Canister (1 Recommended)	327122	Fleet Pump & Service Group, Inc.	\$27.70
7-39	Tube, 1/4 diameter Viton	327030	Fleet Pump & Service Group, Inc.	\$21.50
7-40	Cap Removal Tool (UV3 + Wiper End Cap Tool)	327126	Fleet Pump & Service Group, Inc.	\$58.00
7-41	Plug, Rubber Wiper Filler (Top vent and bottom filler) (Qty 2 per module)	327095	Fleet Pump & Service Group, Inc.	\$58.00
7-42	Screw, Top Vent (Sensor Only)	O10313-AAF063160	Fleet Pump & Service Group, Inc.	\$4.20
7-43	Washer, Upper and Lower brackets	O10116	Fleet Pump & Service Group, Inc.	\$0.89
7-44	Lock Washer, Drive Bar Mount, 1/4"	O10035	Fleet Pump & Service Group, Inc.	\$2.05
7-45	Screw, Drive Bar Mount	O10362	Fleet Pump & Service Group, Inc.	\$2.85
7-46	Valve, Rubber Wiper relief, 4-7 PSI	445044	Fleet Pump & Service Group, Inc.	\$30.00
7-47	Adaptor, Pressure Relief	327765	Fleet Pump & Service Group, Inc.	\$0.65
7-48	Washer, Flat	O12071	NO AWARD	
7-49	Module Board Kit	914385	Fleet Pump & Service Group, Inc.	\$165.00

			Vendor	Price/Percentage
7-50	Board, UV3 + MCB 220-227V	912356-001	NO AWARD	
7-51	Desiccant, DESI PAK 1/6 Unit	302366	NO AWARD	
7-52	Lubricant, Dow 111 5 g Pak	OO3084	NO AWARD	
7-53	Seal, End Cap Ballast Enclosure UV3+ (1 recommended)	316479	NO AWARD	
7-54	INSTN, Module Board Replacement	914383	NO AWARD	
7-55	Ballast Kit (1 Recommended, 4 ballast supplied with system)	914384	NO AWARD	
7-56	Ballast, UV3+ Standard	903988-001	NO AWARD	
7-57	Desiccant, DESI PAK 1/6 UNIT	302366	NO AWARD	
7-58	Lubricant, Dow 111 5 g Pack	OO3084	NO AWARD	
7-59	Strain Relief, 1/2" C/W O-ring	302456	Fleet Pump & Service Group, Inc.	\$16.00
7-60	Screw, 5/16-18x1/2" Allen Head	303314	Fleet Pump & Service Group, Inc.	\$1.75
7-61	O-Ring 1/4 x 3/32 Nitrile UL	002226-108UL	Fleet Pump & Service Group, Inc.	\$6.30
7-62	Desiccant, DESI PAK 1/6 UNIT	302366	NO AWARD	
7-63	Instruction, UV3 + End cap replacement	316492	NO AWARD	
7-64	Spacer Clips	329226	Fleet Pump & Service Group, Inc.	\$3.05
7-65	Screw (Spacer Clip) 6-32x3/5 S- Tap Phillips	O10011	Fleet Pump & Service Group, Inc.	\$1.02
7-66	Hydraulic Filter (1 Recommended)	907384	Fleet Pump & Service Group, Inc.	\$41.00
7-67	Contactora, 12A Schneider Mini	914287	Fleet Pump & Service Group, Inc.	\$35.00
7-68	Contactora, O/L 380-480V	914289-003	Fleet Pump & Service Group, Inc.	\$19.00
7-69	Contactora, O/L 208V	914289-005	Fleet Pump & Service Group, Inc.	\$20.00
7-70	PLC, TWIDO, compact 2410	913292-110	Fleet Pump & Service Group, Inc.	\$215.00
7-71	Fuse Block, 1P	912579	Fleet Pump & Service Group, Inc.	\$21.75
7-72	Fuse Block, 3P	912789	Fleet Pump & Service Group, Inc.	\$64.34
7-73	Fuse, 6A Class CC (1 Recommended, 24 supplied with system)	913838	Fleet Pump & Service Group, Inc.	\$11.00
7-74	Fuse, 4A Class CC (1 Recommended, 24 supplied with system)	912932	Fleet Pump & Service Group, Inc.	\$11.07
7-75	Hydraulic fluid, Tellus, 20L (1 Recommended, 1 Supplied with system for commissioning)	444295	Fleet Pump & Service Group, Inc.	\$215.00
7-76	Gas Door Struts - 30 lb	901711-30	Fleet Pump & Service Group, Inc.	\$43.66
7-77	Gas Door Struts - 40 lb	901711-40	NO AWARD	
7-78	Gas Door Struts - 50 lb	901711-50	NO AWARD	
7-79	Gas Door Struts - 60 lb	901711-60	NO AWARD	
7-80	Low Level Sensor Module 24 VDC	914345-001	Fleet Pump & Service Group, Inc.	\$192.00

			Vendor	Price/Percentage
7-81	Power Supply, 10A 24 VDC	914277	Fleet Pump & Service Group, Inc.	\$181.00
7-82	Relay 16A 3P Touch Safe (1 recommended, 24 supplied with system)	914341	Fleet Pump & Service Group, Inc.	\$20.00
7-83	Relay, 15A Base	912806	Fleet Pump & Service Group, Inc.	\$10.27
7-84	Receptavle, UV3 + 2007	914343	Fleet Pump & Service Group, Inc.	\$85.00
7-85	Receptavle, UV3 + PDC cap	914368	Fleet Pump & Service Group, Inc.	\$16.00
7-86	Fuse Block, 1 P	912579	NO AWARD	
7-87	Fuse Block, 3P	912789	NO AWARD	
7-88	Fuse, 15A class CC (1 recommended, 24 supplied with system)	913420	Fleet Pump & Service Group, Inc.	\$6.25
7-89	Fuse, 6A Class CC (1 Recommended, 24 supplied with system)	912333	Fleet Pump & Service Group, Inc.	\$6.15
7-90	Board ASY, UV3+CCB (kit)	931092	Fleet Pump & Service Group, Inc.	\$1,414.73
7-91	Board, UV3+CCB (See 7-90)	931086	NO AWARD	
7-92	ActicleanGel (1 Recommended, 1 Supplied with system)	901507	Fleet Pump & Service Group, Inc.	\$171.00
7-93	Pressure Injector, Gel UV3 + PLG	327096	Fleet Pump & Service Group, Inc.	\$224.00
7-94	Injector Tip Fitting, 90 degree Elbow (See 7-37)	327066	NO AWARD	
7-95	Safeguard M-1, Rust inhibitor (kit) (1 Recommended 1 supplied with system)	331004	NO AWARD	
7-96	Safeguard M-1, Rust inhibitor, 0.95L	331003	NO AWARD	
7-97	Bottle Spray, Polyethylene	110156	NO AWARD	
7-98	Sensor ASSY, UV3 + NIST9c/w box	015393-S-158NB	Fleet Pump & Service Group, Inc.	\$1,995.00
7-99	Sensor Shipping Box	O15378	NO AWARD	
7-100	Sensor Rear Mount Kit (Complete with Cable ASSY) (See 7-98)	O15393-S-158NB	NO AWARD	
7-101	Sensor Rear Mount Kit (No Cable ASSY)	O15403-002	Fleet Pump & Service Group, Inc.	\$258.07
7-102	Sensor Cable Kit, UV3 + NIST (c/w cable and grommet)	O15406	Fleet Pump & Service Group, Inc.	\$130.00
7-103	Sensor Mount screw, #8-32x1/2"	O10330-83A8C1088	Fleet Pump & Service Group, Inc.	\$0.77
7-104	Lock washer, #8 (for retaining screw)	700126	Fleet Pump & Service Group, Inc.	\$0.51
7-105	Sensor Sleeve	O15239	Fleet Pump & Service Group, Inc.	\$127.00
7-106	Washer, Sensor Sleeve	O15244	Fleet Pump & Service Group, Inc.	\$6.10
7-107	O-Ring, Sleeve Seal (1 recommended) (See 7-13)	316144	NO AWARD	
7-108	Sleeve Cup Nut (See 7-11)	316148	NO AWARD	

			Vendor	Price/Percentage
7-109	Bracket ASSY, 4.0" Spacing	O15237-400	Fleet Pump & Service Group, Inc.	\$43.50
7-110	Sensor Cable Kit Trojan (See-102)	15406	NO AWARD	
7-111	Uv3+ccb processor board Trojan (See 7-90)	931087	NO AWARD	
7-112	Any part not listed for the Trojan 3000 plus UV	N/A	NO AWARD	
Section #8: Aqua-Aerobic System (AquaSBR) Sequencing Batch Reactor Price per Unit				
Item #	Description	Part #		
8-1	Actuator, Limitorque Accutronix, Model LY 2001 (115 VAC)	91070453047	GP Jager Inc.	\$13,271.93
8-2	Actuator, Limitorque Accutronix, Model LY-3001 (115 VAC)	91070453048	GP Jager Inc.	\$13,794.03
8-3	Actuator, Limitorque Accutronix, Model MX (460 VAC)	91070453049	GP Jager Inc.	\$21,609.25
8-4	Level Transducer, Keller Model 700	2610523	GP Jager Inc.	\$828.70
8-5	Linear Actuator, 1500#	2603972	GP Jager Inc.	\$1,199.49
8-6	Capacitor, 35 MFU	2605100	GP Jager Inc.	\$105.06
8-7	Limit Switch (Micro Switch)	26007598	GP Jager Inc.	\$615.08
8-8	Limit Switch Level Arm	2600926	GP Jager Inc.	\$43.32
8-9	Membrane Kit (Gummi-Jager)	2962546	GP Jager Inc.	\$36.74
8-10	Seal Grommet, #S-114	2609887	GP Jager Inc.	\$4.52
8-11	Upper Wedge Cap, #W-114	2609885	GP Jager Inc.	\$11.26
8-12	Pincer, Straight Jaw (Oetiker)	2608035	GP Jager Inc.	\$38.32
8-14	Touch Up Kit - Tenemec 46H-413	91070453055	GP Jager Inc.	\$201.92
8-15	In Put Card, 16 Point Relay	2607722	GP Jager Inc.	\$339.58
8-16	Analog Input Card, 8 Point	2750148	GP Jager Inc.	\$1,055.02
8-17	Power Supply, IO Rach	2608994	GP Jager Inc.	\$747.92
8-18	Panelview 1000 Display	2701264	GP Jager Inc.	\$9,295.71
8-19	Control Relay, SPDT	2700940	GP Jager Inc.	\$19.42
8-20	EEPROM	2750267	GP Jager Inc.	\$595.94
8-21	SLC 5/04 Programmable Controller	2700703	GP Jager Inc.	\$2,676.20
8-22	Any part not listed for the Aqua-Aerobic system (AquaSBR) Sequencing Batch Reactor) - % Above Manufacturers List Cost Letterhead Quote	N/A	GP Jager Inc.	0%

			Vendor	Price/Percentage
Section #9: Xylem brand Flygt pumps				
Parts and Labor:				
9-1	Percentage off Manufacturers List Price for materials		Fleet Pump & Service Group, Inc.	5%
9-2	Labor Cost to Repair Listed			
9-2a	Mechanic - /HR		Fleet Pump & Service Group, Inc.	\$125.00
	Helper - /HR		Fleet Pump & Service Group, Inc.	\$125.00
9-2b	Labor Rates (Weekends and			
	Mechanic - /HR		Fleet Pump & Service Group, Inc.	\$187.50
	Helper - /HR		Fleet Pump & Service Group, Inc.	\$187.50
Section 10: Aerzen USA Corporation Blower Model # GM 25S - 00 DN-125 Pressure				
10-1	Percentage off Manufacturers List Price for materials Letterhead Quote		Rapid Pump & Meter Service Co. Inc.	25%
Section 11: Supply parts for Atlas Copco Stationary compressors ZS 75+ VSD APF176732				
11-1	Percentage off Manufacturers List Price for materials		NO AWARD	
Section 12: Komline-Sanderson Gravabelt GSC-2 Series #3 S-3935 Belt Filter Press				
12-1	Percentage off Manufacturers List Price for materials Letterhead Quote		NO AWARD	
Section #13: Supply parts for Duperon Corporation FlexRake FPFS Mechanically Cleaned Bar Screens S/N 914-1310-w2607-1, and 2				
13-1	Percentage off Manufacturers List Price for materials Letterhead Quote		Koester Associates, Inc.	0%
Section #14: Supply parts for Aurora pump Model # 612a 8x8x15a, and Models 341A, 342A, and 344A				
14-1	Percentage off Manufacturers List Price for materials Letterhead Quote		Rapid Pump & Meter Service Co. Inc.	25.0%
Section #15: Supply parts for Komline-Sanderson K-S Plunger Pump Model # KSK-9-1 S/N 9KSK-43, and 9KSK-44				
15-1	Percentage off Manufacturers List Price for materials Letterhead Quote		NO AWARD	
Section #16: Supply parts for Fairfield Cantenary Bar Screen (CHCFF) MN 80-31338 dated 12/12/14				
16-1	Percentage off Manufacturers List Price for materials Letterhead Quote		GP Jager Inc.	0%

			Vendor	Price/Percentage
Section #17: Supply parts for Duperon Corporation Washer Compactor SN: 202-1408-w2805-1				
17-1	Percentage off Manufacturers List Price for materials Letterhead Quote		Koester Associates, Inc.	0%
Section #18: Supply parts for Schloss Enginered Equipment Inc. Grit Chamber Dewatering Screw Project No. 1780-14				
18-1	Percentage off Manufacturers List Price for materials Letterhead Quote		Koester Associates, Inc.	0%