



Town Hall · 100 Main Street
Huntington, NY 11743-6991

Phone: (631) 351-3177
Fax: (631) 351-2833
<http://HuntingtonNY.gov>

Lori E. Finger, CPPB
Director of Purchasing

For additional information contact
purchasing@huntingtonny.gov

Denise Gallo
Purchasing Agent

**AWARD: REPLACEMENT AND OR REPAIRS OF VARIOUS WASTEWATER
TREATMENT PLANT EQUIPMENT PARTS-SELECTED ITEMS
BID NO. TOH 16-09R-046
BID OPENED: 09/29/16
CONTRACT PERIOD: 10/06/16 TO AND INCLUDING 09/30/17
CATEGORY #9: ENVIRONMENTAL SERVICES, RECYCLING AND REFUSE
SERVICES
ALL PRICES ARE FOB TOWN OF HUNTINGTON**

AWARDEES:

#9797	G.P. Jager, Inc. P.O. Box 50 Boonton, NJ 07005 Attn: Zuzanna Stolc, Office Manager	Tel: 973-750-1180 Fax: 973-750-1181 zstolc@jagerinc.com
#1015	Fleet Pump & Service Group, Inc. 455 Knollwood Road White Plains, NY 10603 Attn: Mark Cavanagh	Tel: 914-835-3801 Fax: 914-835-2946 mcavanagh@fleetpump.com

Pursuant to New York General Municipal Law §103(16), the contract awarded hereby shall be made available to other New York State governmental entities and, therefore, any New York State officer, board or agency of a political subdivision or of any district therein authorized to make purchases of apparatus, materials, equipment or supplies, or to contract for services related to the installation, maintenance, or repair of apparatus, materials, equipment or supplies, may make such purchases, or may contract for such services through the use of this contract. Said entities using this contract shall be wholly responsible for the determination that the contract meets their requirements and for the issuance of said contract and shall be solely responsible for the payment of any and all debts and claims that arise thereunder.



					Vendor	Price/ Percentage
Section #1: Supply replacement parts for BDP belt press parts 1.5m BDP (Job # 760) belt filter price (1987) Price per Unit Parts:						
BDP MANUFAC- TURED WEAR ITEMS	REQD PER PRESS	MANUFAC- TURER	PART NUMBER	DESCRIPTION		
1-1	1	BDP	3-610-524 (P2)	SET OF (2) DOCTOR BLADES	Fleet Pump & Service Group, Inc.	\$160.00
1-2	1	BDP	1-BDP-0025	FEEDBOX SEAL	Fleet Pump & Service Group, Inc.	\$145.00
1-3	1	BDP	3-610-1120	SET OF (2) GUIDE RAIL SEALS	Fleet Pump & Service Group, Inc.	\$108.00
1-4	1	BDP	1-BDP-0032 (60")	SET OF (2) TOP SHOWER SEALS	Fleet Pump & Service Group, Inc.	\$200.00
1-5	1	BDP	1-BDP-0033 (60")	SET OF (4) BOTTOM SHOWER SEALS	Fleet Pump & Service Group, Inc.	\$345.00
1-6	2	BDP	3-310-89	TRACKING SLIDE PLATES	Fleet Pump & Service Group, Inc.	\$108.00
1-7	4	BDP	3-610-842 (P1)	TRACKING PADDLE	Fleet Pump & Service Group, Inc.	\$102.00
1-8	5	BDP	3-650-74	3" NYLON TABLE ROLL	Fleet Pump & Service Group, Inc.	\$1,545.00
1-9	12	BDP	3-610-871	6" NYLON COMPRESSIO N/IDLER ROLL	Fleet Pump & Service Group, Inc.	\$2,580.00
1-10	2	BDP	3-610-1238	6" NITRILE TRACKING ROLL	Fleet Pump & Service Group, Inc.	\$2,755.00
1-11	6	BDP	3-610-1049	8" NYLON COMPRESSIO N/IDLER ROLL	Fleet Pump & Service Group, Inc.	\$3,110.00
1-12	3	BDP	3-610-963	10" NYLON COMPRESSIO N/IDLER ROLL	Fleet Pump & Service Group, Inc.	\$4,050.00
1-13	1	BDP	3-610-1615	20" NITRILE DRIVE ROLL	Fleet Pump & Service Group, Inc.	\$6,580.00
1-14	1	BDP	2-610-165	24" PERFORATED ROLL	Fleet Pump & Service Group, Inc.	\$12,400.00

					Vendor	Price/ Percentage
1-15	N/A	Any part not listed for BDP belt press - % Above Manufacturers List Cost			Fleet Pump & Service Group, Inc.	0%
Section #2: Flowserve Actuator Limitorque Accutronix Parts and Labor:						
2-1	Percentage off Manufacturers List Price for materials				NO AWARD	
2-2	Labor Cost to Repair Listed Equipment					
2-2a	Mechanic: /HR				NO AWARD	
	Helper: /HR				NO AWARD	
2-2b	Labor Rates (Weekends and Holidays)					
	Mechanic: /HR				NO AWARD	
	Helper: /HR				NO AWARD	
Section #3: Envirosight Rovver 5.0 Motorized Robotic Color Camera. Rover 600 and TR 150 Parts and Labor:						
3-1	Percentage off Manufacturers List Price for materials				NO AWARD	
	Labor Cost to Repair Listed Equipment					
3-2	Bench Charge: /HR				NO AWARD	
Section #4: Penn Valley Model 4" Double Disc Pump - Price Per Unit						
Item #	Description		Part#			
9-1	Suction Housing		PVC101		NO AWARD	
9-2	Intermediate Housing		PVC102		NO AWARD	
9-3	Discharge Housing		PVC103		NO AWARD	
9-4	Swan Neck , Cast Iron		PVC104		NO AWARD	
9-5	Pedestal		PVB106		NO AWARD	
9-6	Center Support		PVB107		NO AWARD	
9-7	Drive Shaft		PVB108		NO AWARD	
9-8	Cam Lobe		PVA109		NO AWARD	
9-9	Con Rod Suction		PVC110A		NO AWARD	
9-10	Con Rod , Discharge		PVC110B		NO AWARD	
9-11	Drive Rod , Suction		PVA111		NO AWARD	
9-12	Drive Rod , Discharge		PVA112		NO AWARD	
9-13	Trunnion		PVB113		NO AWARD	
9-14	Trunnion Clamp Ring , Suction		PVB114A		NO AWARD	

					Vendor	Price/ Percentage
9-15	Trunnion Clamp Ring , Discharge	PVB114B			NO AWARD	
9-16	Integral Disc, Suction	PVC188 or PVD632			NO AWARD	
9-17	Integral disc, Discharge	PVC160 or PVD633			NO AWARD	
9-18	Gasket , Suction	PVB119			NO AWARD	
9-19	Gasket , Discharge	PVB120			NO AWARD	
9-20	Clack Valve	PVB121			NO AWARD	
9-21	Clack Valve Spacer	PVA122			NO AWARD	
9-22	Special Washer	PVA138			NO AWARD	
9-23	Drive Pin	PVA182			NO AWARD	
9-24	Bearing Con Rod	PVA242			NO AWARD	
9-25	Bearing Pedestal	PVA245			NO AWARD	
9-26	Drive Cover	PVB123			NO AWARD	
9-27	Priming/Drain Plug	PVA180			NO AWARD	
9-28	1/2"-13 UNCx5" Bolt	PVA390			NO AWARD	
9-29	1/2"-13 UNCx3-1/4" Bolt	PVA389			NO AWARD	
9-30	1/2"-13 UNCx2-1/4" Bolt	PVA388			NO AWARD	
9-31	1/2"-13 UNC Nut	PVA386			NO AWARD	
9-32	1/2" Flat Washer	PVA385			NO AWARD	
9-33	1/2" Lock Washer	PVA384			NO AWARD	
9-34	1/2"-13 UNC x 2" Bolt	PVA387			NO AWARD	
9-35	5/16"-18x3/4" Bolt	PVA383			NO AWARD	
9-36	5/16" Flat Washer	PVA382			NO AWARD	
9-37	5/16" Lock Washer	PVA381			NO AWARD	
Section #7: Supply replacement for Trogan UV3000 Plus unit						
Price Per Unit						
Item #	Description	Part #				
7-1	Lamp holder, Amalgam 4 wire 60"	316135-060			NO AWARD	
7-2	Lamp holder, Amalgam 4 wire 78"	316135-078			NO AWARD	
7-3	Lamp holder, Amalgam 4 wire 96"	316135-096			NO AWARD	
7-4	Lamp holder, Angular Amalgam 4 wire 60" New No.: 316505-060X	316473-060			Fleet Pump & Service Group, Inc.	\$47.00
7-5	Lamp holder, Angular Amalgam 4 wire 78"	316473-078			Fleet Pump & Service Group, Inc.	\$51.00

					Vendor	Price/ Percentage
7-6	Lamp holder, Angular Amalgam 4 wire 96" New No.: 316505-096X		316473-096		Fleet Pump & Service Group, Inc.	\$67.85
7-7	Lamp, Hareus Amalgam (salmon colored base) (4 recommended, 24 supplied with system)		794447		Fleet Pump & Service Group, Inc.	\$325.00
7-8	Sleeve, Quartz, 28mmx25mmx1850mm domed, flared (4 Pack)		316136		Fleet Pump & Service Group, Inc.	\$415.00
7-9	Plug, UV3 + PDC Module 6'		914374-006		Fleet Pump & Service Group, Inc.	\$97.75
7-10	Spring, SS Compression (Pkg. of 10) New No.: 901376P		901376		Fleet Pump & Service Group, Inc.	\$60.00
7-11	Sleeve cup nut (Pkg. of 10) New No.: 316148P		316148		Fleet Pump & Service Group, Inc.	\$31.00
7-12	O-Ring Seal (End cap ballast seal) *Pkg. of 10) New No.: 316509		316168		Fleet Pump & Service Group, Inc.	\$45.00
7-13	O-Ring, Sleeve Support (4 Recommended) (Pkg. of 10) New No. 316144P)		316144		Fleet Pump & Service Group, Inc.	\$1.43
7-14	O-Ring, Sleeve Support		316145		Fleet Pump & Service Group, Inc.	\$0.10
7-15	Coupling, Female		013168-04FST		NO AWARD	
7-16	Coupling, Male		013169-04MST		NO AWARD	
7-17	Rubber Dust Collector, Female Coupling		013199-04F		NO AWARD	
7-18	Rubber Dust Collector, Male Coupling		013200-04M		NO AWARD	
7-19	Hydraulic Hose ASY, Retract, LS (Black)		907424- 04F071BK		NO AWARD	
7-20	Hydraulic Hose ASY, Extend, LS (Black)		907424- 04M150BK		NO AWARD	
7-21	Hydraulic Hose ASSY, Retract, RS (Blue)		907424- 04F145BL		NO AWARD	
7-22	Hydraulic Hose ASSY, Extend, RS (Blue)		907424- 04M066BL		NO AWARD	
7-23	Hydraulic Tube Extend, SS, 4 Lamp Modules New No.: 326417-440		326417-430-435- 440		Fleet Pump & Service Group, Inc.	\$29.00
7-24	Hydraulic Tube Retract, SS, 4 Lamp Modules New No.: 326418-440		326418-430-435- 440		Fleet Pump & Service Group, Inc.	\$29.00
7-25	Nut, Locking Bar Lock Brackets New No.: 011047		O11047		Fleet Pump & Service Group, Inc.	\$0.07
7-26	Screw, Lock Brackets and Drive Bar Mount		010314- AAf083160		Fleet Pump & Service Group, Inc.	\$0.52
7-27	Lock Washer, Sensor Drive Bar Brackets New No.: 012014P		O12014		Fleet Pump & Service Group, Inc.	\$0.22

				Vendor	Price/ Percentage
7-28	Wiper Bracket, Upper	327766-UPR	Fleet Pump & Service Group, Inc.	\$9.50	
7-29	Wiper Bracket, Lower	327766-LWR	Fleet Pump & Service Group, Inc.	\$9.50	
7-30	Bracket, Sensor Lock	327132	Fleet Pump & Service Group, Inc.	\$0.79	
7-31	Lock Plate, Drive Bar	327130	Fleet Pump & Service Group, Inc.	\$1.75	
7-32	Cylinder, Wiper	326411	Fleet Pump & Service Group, Inc.	\$1,334.00	
7-33	Grease, Food Grade (1 Recommended, 1 Supplied with System) New No.: 005066	OO5066	Fleet Pump & Service Group, Inc.	\$19.00	
7-34	Grease, Nipple	326399	Fleet Pump & Service Group, Inc.	\$4.70	
7-35	Grease Gun	5067	NO AWARD		
7-36	Fitting, Plastic (2 Per Canister) (Pkg. of 10) New No.: 327027P	327027	Fleet Pump & Service Group, Inc.	\$25.00	
7-37	Fitting, Plastic 90 degree elbow (Pkg. of 10) New No.: 327066P	327066	Fleet Pump & Service Group, Inc.	\$41.00	
7-38	Seal Kit UV3000Plus - Plastic Canister (1 Recommended)	327122	Fleet Pump & Service Group, Inc.	\$24.40	
7-39	Tube, 1/4 diameter Viton 12"	327030	Fleet Pump & Service Group, Inc.	\$6.12	
7-40	Cap Removal Tool (UV3 + Wiper End Cap Tool)	327126	Fleet Pump & Service Group, Inc.	\$19.40	
7-41	Plug, Rubber Wiper Filler (Top vent and bottom filler) (Qty 2 per module) (Pkg. of 10) New No.: 327095P	327095	Fleet Pump & Service Group, Inc.	\$14.55	
7-42	Screw, Top Vent (Sensor Only)	O10313-AAFO63160	Fleet Pump & Service Group, Inc.	\$0.50	
7-43	Washer, Upper and Lower brackets	O10116	Fleet Pump & Service Group, Inc.	\$0.19	
7-44	Lock Washer, Drive Bar Mount, 1/4"	O10035	Fleet Pump & Service Group, Inc.	\$0.28	
7-45	Screw, Drive Bar Mount	O10362	Fleet Pump & Service Group, Inc.	\$1.21	
7-46	Valve, Rubber Wiper relief, 4-7 PSI	445044	NO AWARD		
7-47	Adaptor, Pressure Relief (New No.: 327795)	327765	Fleet Pump & Service Group, Inc.	\$5.25	
7-48	Washer, Flat	O12071	NO AWARD		
7-49	Module Board Kit	914385	Fleet Pump & Service Group, Inc.	\$165.00	
7-50	Board, UV3 + MCB 220-227V	912356-001	NO AWARD		
7-51	Desiccant, DESI PAK 1/6 Unit	302366	NO AWARD		
7-52	Lubricant, Dow 111 5 g Pak	OO3084	NO AWARD		
7-53	Seal, End Cap Ballast Enclosure UV3+ (1 recommended)	316479	NO AWARD		

				Vendor	Price/ Percentage
7-54	INSTN, Module Board Replacement	914383		NO AWARD	
7-55	Ballast Kit (1 Recommended, 4 ballast supplied with system)	914384		NO AWARD	
7-56	Ballast, UV3+ Standard New No.: 915378	903988-001		Fleet Pump & Service Group, Inc.	\$784.00
7-57	Desiccant, DESI PAK 1/6 UNIT	302366		NO AWARD	
7-58	Lubricant, Dow 111 5 g Pack	003084		NO AWARD	
7-59	Strain Relief, 1/2" C/W O-ring New No.: 914478-129	302456		Fleet Pump & Service Group, Inc.	\$7.70
7-60	Screw, 5/16-18x1/2" Allen Head New No.: 010313-AGC10316	303314		Fleet Pump & Service Group, Inc.	\$0.25
7-61	O-Ring 1/4 x 3/32 Nitrile UL New No.: 002226-108ULP	002226-108UL		Fleet Pump & Service Group, Inc.	\$1.25
7-62	Desiccant, DESI PAK 1/6 UNIT	302366		NO AWARD	
7-63	Instruction, UV3 + End cap replacement	316492		NO AWARD	
7-64	Spacer Clips	329226		Fleet Pump & Service Group, Inc.	\$3.05
7-65	Screw (Spacer Clip) 6-32x3/5 S- Tap Phillips	O10011		Fleet Pump & Service Group, Inc.	\$0.06
7-66	Hydraulic Filter (1 Recommended)	907384		Fleet Pump & Service Group, Inc.	\$40.00
7-67	Contactora, 12A Schneider Mini	914287		Fleet Pump & Service Group, Inc.	\$31.40
7-68	Contactora, O/L 380-480V	914289-003		Fleet Pump & Service Group, Inc.	\$16.35
7-69	Contactora, O/L 208V	914289-005		Fleet Pump & Service Group, Inc.	\$16.95
7-70	PLC, TWIDO, compact 2410	913292-110		Fleet Pump & Service Group, Inc.	\$215.00
7-71	Fuse Block, 1P New No.: 914768- 110	912579		Fleet Pump & Service Group, Inc.	\$9.90
7-72	Fuse Block, 3P New No.: 914768- 310	912789		Fleet Pump & Service Group, Inc.	\$30.20
7-73	Fuse, 6A Class CC (1 Recommended, 24 supplied with system) New No.: 914568-060	913838		Fleet Pump & Service Group, Inc.	\$4.30
7-74	Fuse, 4A Class CC (1 Recommended, 24 supplied with system) New No.: 914568-040	912932		Fleet Pump & Service Group, Inc.	\$5.65
7-75	Hydraulic fluid, Tellus, 20L (1 Recommended, 1 Supplied with system for commissioning)	444295		Fleet Pump & Service Group, Inc.	\$215.00
7-76	Gas Door Struts - 30 lb	901711-30		Fleet Pump & Service Group, Inc.	\$45.50
7-77	Gas Door Struts - 40 lb	901711-40		NO AWARD	

				Vendor	Price/ Percentage
7-78	Gas Door Struts - 50 lb	901711-50		NO AWARD	
7-79	Gas Door Struts - 60 lb	901711-60		NO AWARD	
7-80	Low Level Sensor Module 24 VDC	914345-001		Fleet Pump & Service Group, Inc.	\$163.50
7-81	Power Supply, 10A 24 VDC New No.: 916051-459	914277		Fleet Pump & Service Group, Inc.	\$124.00
7-82	Relay 16A 3P Touch Safe (1 recommended, 24 supplied with system)	914341		Fleet Pump & Service Group, Inc.	\$14.05
7-83	Relay, 15A Base	912806		Fleet Pump & Service Group, Inc.	\$10.50
7-84	Receptavle, UV3 + 2007	914343		Fleet Pump & Service Group, Inc.	\$55.00
7-85	Receptavle, UV3 + PDC cap	914368		Fleet Pump & Service Group, Inc.	\$9.80
7-86	Fuse Block, 1 P	912579		NO AWARD	
7-87	Fuse Block, 3P	912789		NO AWARD	
7-88	Fuse, 15A class CC (1 recommended, 24 supplied with system) New No.: 914569-150	913420		Fleet Pump & Service Group, Inc.	\$5.70
7-89	Fuse, 6A Class CC (1 Recommended, 24 supplied with system) New No.: 914569-060	912333		Fleet Pump & Service Group, Inc.	\$4.35
7-90	Board ASY, UV3+CCB (kit) (Board Kit, UV3+CCB) New No.: 931096	931092		Fleet Pump & Service Group, Inc.	\$1,601.00
7-91	Board, UV3+CCB	931086		Fleet Pump & Service Group, Inc.	SEE 7-90
7-92	Acticlean Gel (1 Recommended, 1 Supplied with system)	901507		Fleet Pump & Service Group, Inc.	\$171.00
7-93	Pressure Injector, Gel UV3 + PLG	327096		Fleet Pump & Service Group, Inc.	\$224.00
7-94	Injector Tip Fitting, 90 degree Elbow	327066		Fleet Pump & Service Group, Inc.	SEE 7-37
7-95	Safeguard M-1, Rust inhibitor (kit) (1 Recommended 1 supplied with system)	331004		NO AWARD	
7-96	Safeguard M-1, Rust inhibitor, 0.95L	331003		NO AWARD	
7-97	Bottle Spray, Polyethylene	110156		NO AWARD	
7-98	Sensor ASSY, UV3 + NIST9c/w box	015393-S- 158NB		Fleet Pump & Service Group, Inc.	\$1,995.00
7-99	Sensor Shipping Box	O15378		NO AWARD	
7-100	Sensor Rear Mount Kit (Complete with Cable ASSY)	O15393-S- 158NB		Fleet Pump & Service Group, Inc.	SEE 7-98
7-101	Sensor Rear Mount Kit (No Cable ASSY)	O15403-002		Fleet Pump & Service Group, Inc.	\$258.07

					Vendor	Price/ Percentage
7-102	Sensor Cable Kit, UV3 + NIST (c/w cable and grommet)	O15406			Fleet Pump & Service Group, Inc.	\$130.00
7-103	Sensor Mount screw, #8-32x1/2"	O10330-83A8C1088			Fleet Pump & Service Group, Inc.	\$0.77
7-104	Lock washer, #8 (for retaining screw)	700126			Fleet Pump & Service Group, Inc.	\$0.51
7-105	Sensor Sleeve	O15239			Fleet Pump & Service Group, Inc.	\$127.00
7-106	Washer, Sensor Sleeve	O15244			Fleet Pump & Service Group, Inc.	\$6.10
7-107	O-Ring, Sleeve Seal (1 recommended)	316144			Fleet Pump & Service Group, Inc.	SEE 7-13
7-108	Sleeve Cup Nut	316148			Fleet Pump & Service Group, Inc.	SEE 7-11
7-109	Bracket ASSY, 4.0" Spacing	O15237-400			Fleet Pump & Service Group, Inc.	\$43.50
7-110	Sensor Cable Kit Trojan	15406			Fleet Pump & Service Group, Inc.	SEE 7-102
7-111	Uv3+ccb processor board Trojan	931087			Fleet Pump & Service Group, Inc.	SEE 7-90
7-112	Any part not listed for the Trojan 3000 plus UV	N/A			Fleet Pump & Service Group, Inc.	0%

				Vendor	Price/ Percentage
Section #9: Xylem brand Flygt pumps					
Parts and Labor:					
9-1	Percentage off Manufacturers List Price for materials		Fleet Pump & Service Group, Inc.	5%	
9-2	Labor Cost to Repair Listed Equipment				
9-2a	Mechanic - /HR		Fleet Pump & Service Group, Inc.	\$125.00	
	Helper - /HR		Fleet Pump & Service Group, Inc.	\$125.00	
9-2b	Labor Rates (Weekends and Holidays)				
	Mechanic - /HR		Fleet Pump & Service Group, Inc.	\$250.00	
	Helper - /HR		Fleet Pump & Service Group, Inc.	\$250.00	
Section 11: Supply parts for Atlas Copco Stationary compressors ZS 75+ VSD APF176732					
11-1	Percentage off Manufacturers List Price for materials		NO AWARD		
Section 12: Komline-Sanderson Gravabelt GSC-2 Series #3 S-3935 Belt Filter Press					
12-1	Percentage off Manufacturers List Price for materials		G.P. Jager, Inc.	0%	
Section #15: Supply parts for Komline-Sanderson K-S Plunger Pump Model # KSK-9-1 S/N 9KSK-43, and 9KSK-44					
15-1	Percentage off Manufacturers List Price for materials		G.P. Jager, Inc.	0%	