

APPENDIX B

**COMMUNITY CHARACTER-RELATED
DOCUMENTATION**

**Appendix B-1
Photographs of Study Area**



APPENDIX B-1 PHOTOGRAPH LOCATION MAP

Source: NYS Orthoimagery Program, 2013
Scale: 1 inch = 225 feet



Renaissance
Revitalization Project,
Huntington Station

VEIS

Renaissance Revitalization Project
Photos taken July 2014



1. View of Railroad Street, looking west



2. View of Community First Aid Squad on Railroad Street



3. View of Parcel 1, looking southeast



4. View of existing conditions on Parcel 1

Renaissance Revitalization Project
Photos taken July 2014



5. View of Parcel 1, looking south from Railroad Street



6. View of intersection of 110 and Broadway, looking southeast



7. View of Parcel 4 from Broadway



8. View looking north on 110



9. View of Parcel 4, looking south on 110



10. View of Town Historic Inventory #2 on east side of 110



11. View of Town Historic Inventory #3 on east side of 110



12. View of 110, looking south

Renaissance Revitalization Project
Photos taken July 2014



13. View of vacant area on northeast corner of Northridge Street and 110



14. View of 110, looking north towards Yankee Peddler



15. View of commercial facilities on Broadway, looking south



View of Yankee Peddler building Town Historic Inventory #4
on east side of 110)

Renaissance Revitalization Project
Photos taken July 2014



17. View of Auto Parts store on Parcel 7, looking south



18. View of existing buildings on Parcel 7, looking north



19. View of Parcel 7 and 110, looking south



20. View of vacant area on Parcel 7

Renaissance Revitalization Project
Photos taken July 2014



21. View of public seating area on east side of 110, near Parcel 7



22. View of existing buildings on Parcel 7, looking north



23. View of existing buildings on Parcel 7



24. View of public seating area on east side of 110, near Parcel 7

Renaissance Revitalization Project
Photos taken July 2014



25. View of northern vacant area on Parcel 7



26. View of Town Historic Inventory #5 on parcel 7



27. View of Parcel 4, looking south



28. View of 110, looking north past the study area

Renaissance Revitalization Project
Photos taken July 2014



29. View of apartments on north side of Woodhull Road



30. View of property on south side of Nassau Road



31. View of residential area on the east side of New York Avenue (Town Historic Inventory #8)



32. View of residential area on the east side of New York Avenue (Town Historic Inventory #8)

Renaissance Revitalization Project
Photos taken July 2014



33. View of residential area on the east side of New York Avenue (Town Historic Inventory #8)



34. View of residential area around Lowndes Avenue (Town Historic Inventory #7)



35. View looking south on Lowndes Avenue towards Railroad Street



View of Huntington train station, Town Historic Inventory #1

Renaissance Revitalization Project
Photos taken July 2014



37. View of parking garage near train station



38. View of residential area south of Broadway



39. View of Town Historic Inventory #6